


HAWKS

Magnesium hawk corners are rounded for safety, comfort and long service. Has 4" flange reinforcing the center. Comes with a special 1/2" thick sponge rubber hand protector. Lighter than aluminum.

No.	Size	Wt (lbs)
TTH H8	8" x 8"	0.90
TTH H10	10" x 10"	1.10
TTH H12	12" x 12"	1.40
TTH H13	13" x 13"	1.60
TTH H14	14" x 14"	1.70



HEATING IRON

HEATING IRON

For PVC waterstop, cut ends square and hold both sides against iron to 350°-380° F. Do not allow the iron to reach 400° F, PVC will degrade and turn dark color. When about 1/4" of material becomes soft and gummy, remove the iron and press ends firmly together. Hold tightly and allow material to cool before applying stress. All center bulb waterstop must be aligned. For TPE Waterstop preheat iron to 380° to 410° F.

No.	Size	Wt (lbs)
GS 214	2" x 12"	5.00
GS 214C	2" x 12" Teflon Cover	0.10
GS 414	4" x 14"	5.00
GS 414C	4" x 14" Teflon Cover	0.10

